



| Code | D1 | L | L2 | L3 | L4 | M | SW | Code | D1 | L | L2 | L3 | L4 | M | SW |
|------------|-----|-----|-----|----|----|-----|-----|------------|----|-----|----|-----|----|-----|----|
| C50MH1460 | 14 | 60 | 25 | 14 | 17 | M8 | 12 | C50MH40220 | 40 | 220 | 55 | 36 | 35 | M20 | 36 |
| C50MH1470 | | 70 | | | | | | C50MH40240 | | 240 | | | | | |
| C50MH1480 | | 80 | | | | | | C50MH40260 | | 260 | | | | | |
| C50MH14100 | | 100 | | | | | | C50MH40300 | | 300 | | | | | |
| C50MH14120 | | 120 | | | | | | C50MH40340 | | 340 | | | | | |
| C50MH14140 | | 140 | | | | | | C50MH40380 | | 380 | | | | | |
| C50MH14160 | | 160 | | | | | | | | | | | | | |
| C50MH14180 | | 180 | | | | | | | | | | | | | |
| C50MH18100 | | 18 | | | | | | 100 | | 30 | | | | | |
| C50MH18120 | 120 | | | | | | | | | | | | | | |
| C50MH18140 | 140 | | | | | | | | | | | | | | |
| C50MH18160 | 160 | | | | | | | | | | | | | | |
| C50MH18180 | 180 | | | | | | | | | | | | | | |
| C50MH18200 | 200 | | | | | | | | | | | | | | |
| C50MH18220 | 220 | | | | | | | | | | | | | | |
| C50MH18240 | 240 | | | | | | | | | | | | | | |
| C50MH20100 | 20 | | 100 | 30 | 18 | 20 | M12 | 17 | | | | | | | |
| C50MH20120 | | 120 | | | | | | | | | | | | | |
| C50MH20140 | | 140 | | | | | | | | | | | | | |
| C50MH20160 | | 160 | | | | | | | | | | | | | |
| C50MH20180 | | 180 | | | | | | | | | | | | | |
| C50MH20200 | | 200 | | | | | | | | | | | | | |
| C50MH20220 | | 220 | | | | | | | | | | | | | |
| C50MH20240 | | 240 | | | | | | | | | | | | | |
| C50MH24120 | | 24 | 120 | | | | | | 35 | 22 | 25 | M12 | 19 | | |
| C50MH24140 | 140 | | | | | | | | | | | | | | |
| C50MH24160 | 160 | | | | | | | | | | | | | | |
| C50MH24180 | 180 | | | | | | | | | | | | | | |
| C50MH24200 | 200 | | | | | | | | | | | | | | |
| C50MH24240 | 240 | | | | | | | | | | | | | | |
| C50MH30180 | 30 | 180 | 45 | 28 | 30 | M16 | 24 | | | | | | | | |
| C50MH30220 | | 220 | | | | | | | | | | | | | |
| C50MH30260 | | 260 | | | | | | | | | | | | | |
| C50MH30300 | | 300 | | | | | | | | | | | | | |
| C50MH40160 | 40 | 160 | 55 | 36 | 35 | M20 | 36 | | | | | | | | |
| C50MH40180 | | 180 | | | | | | | | | | | | | |
| C50MH40200 | | 200 | | | | | | | | | | | | | |